

TECHNICAL SERVICE BULLETIN

Bulletin Nbr: 210-2486 utg.2

Date:.....Mars 2008

Market: all

Cars affected

Saab 9-5 M98- with engine alternative B205 and B235

Background

The centre tensioning roller of the belt circuit has been removed on cars from and including Vehicle Identification Number 43505872. This means that the belt for cars from and including the above Vehicle Identification Number is shorter than the old one.

The old (longer) belt that was previously discontinued is now back in stock again, and this belt must be used for belt replacement on cars up to and including Vehicle Identification Number 43505871.


Parts required

48 99 548 (CA: 30568609) Belt (up to and including Vehicle Identification Number 43505871)

Procedure


For belt replacement, see the illustration for the new belt circuit routing.

New version:



E121R172

Old version:



E210S014

Warranty/Time Information

